

Only the phones listed below will work with the USA SIM Card

Use the **exact model** in this list to see if your phone is supported. There are many versions of the same phone and each version has its specific model number even when the marketing name is the same. For example, Galaxy S20 models G981U and G981U1 **will work**

but Galaxy S20 models G981F, G981N and G981O **will NOT work**

How to determine your phone's model: All iPhones from iPhone 6 and newer will work. For Android phones go to Settings (you may have to go into the System menu next). Tap About Phone or About Device to view the model name and number. For other phones go to Settings and tap About Phone

Apple

iPhone 6 and newer

Samsung

- | | | | | |
|--|---|---|---|--|
| <ul style="list-style-type: none"> Galaxy A71 5G (A716U, A716U1) Galaxy A52 5G (A526U, A526U1) Galaxy A51 5G (A516U, A516U1, A516UP) Galaxy A51 (A515U, A515U1) Galaxy A50 (A505U1, A505A, S506DL) Galaxy A42 5G (A426U1) Galaxy A32 5G SE (A326U, A326U1/DS) Galaxy A21 SE (A215U1) Galaxy A12 SE (A125U, A125U1/DS) Galaxy A11 (A115A, A115AZ, A115AP, A115U1) Galaxy A10e (A102U, A102UC, A102U1) Galaxy A6 (A600A, A600AZ) Galaxy A02 (A025A, A025U1/DS) Galaxy A01 (A015A, SM-A015U1) | <ul style="list-style-type: none"> Galaxy J7 (J727A, J737A) Galaxy J2 Dash (J260A) Galaxy J2 Pure (J260AZ) | <ul style="list-style-type: none"> Galaxy S21 FE (SM-G990U, SM-G990U1) Galaxy S21 5G (G991U, G991U1) Galaxy S21+ 5G (G996U, G996U1) Galaxy S21 Ultra 5G (G998U, G998U1) | <ul style="list-style-type: none"> Galaxy S10 (G973U*, G973UC, G973U1*) Galaxy S10+ (G975U*, G975U1*) Galaxy S10 5G (G977U) Galaxy S10e (G970U*, G970U1*) Galaxy S10 Lite (G770U1) | <ul style="list-style-type: none"> Galaxy XCover FieldPro (G889A) Galaxy XCover Pro (G715U1, G715A) |
| <ul style="list-style-type: none"> Galaxy Express Prime 3 (J337A) Galaxy Express Prime 2/J3 (J327A) Galaxy Express Prime/J3 (J320A) Galaxy Express 3 (J120A) | <ul style="list-style-type: none"> Galaxy Note20 5G (N981U, N981U1) Galaxy Note20 Ultra 5G (N986U, N986U1) Galaxy Note10 (N970U, N970U1*) Galaxy Note10+ (N975U, N975U1*) Galaxy Note10+ 5G (N976U) Galaxy Note9 (N960U*, N960U1*) Galaxy Note8 (N950U*) Galaxy Note5 (N920A) Galaxy Note4 (N910A*) Galaxy Note Edge (N915A*) | <ul style="list-style-type: none"> Galaxy S20 5G (G981U, G981U1) Galaxy S20+ 5G (G986U, G986U1) Galaxy S20 Ultra 5G (G988U, G988U1) Galaxy S20 FE (G781U, G781U1, G781UC) | <ul style="list-style-type: none"> Galaxy S9 (G960U*, G960U1*) Galaxy S9+ (G965U*, G965U1*) Galaxy S8 (G950U*) Galaxy S8 Active (G892A) Galaxy S8+ (G955U*) | <ul style="list-style-type: none"> Galaxy Z Flip FE (SM-F711U, SM-F711U1) Galaxy Z Flip 5G (F707U, F707U1) Galaxy Z Flip (F700U/DS, F700U1) Galaxy Z Fold3 (SM-F926U, SM-F926U1) Galaxy Z Fold2 5G (F916U, F916U1) Galaxy Z Fold (F900U, F900U1) |
| | | | <ul style="list-style-type: none"> Galaxy S7 Edge (G935A) Galaxy S7 (G930A) Galaxy S7 Active (G891A) | |
| | | | <ul style="list-style-type: none"> Galaxy S6 Edge Plus (G928A) Galaxy S6 Edge (G925A) Galaxy S6 (G920A) Galaxy S6 Active (G890A) | |
| | | | <ul style="list-style-type: none"> Galaxy S5 (G900A*) Galaxy S5 Active (G870A) Galaxy S5 Mini (G800A) | |
| | | | <ul style="list-style-type: none"> Galaxy S4 Mini (i257) | |

*Indicates devices that may require a software update to enable HD Voice, Wi-Fi Calling, Video Call, Advanced Messaging or 5G
Last updated: Sept 3, 2021



LG

- Arena 2/Neon Plus (LM-X320APM/AM8)
- Escape Plus (X320CM)
- Escape2 (H443)
- Classic Flip (L125DL)
- Fortune 3 (LMK300AMC)
- G8X (LM-G850QM)
- G8X ThinQ (LM-G850UM)
- G8 ThinQ (LM-G820UM, LM-G820QM*)
- G7 (G710ULM)
- G7 ThinQ (LM-G710ULM)
- G6 (H871S, H871)
- G5 (H820)
- G4 (H810)
- G3* (D850)
- G3 Vigor (D725)
- G Flex 2 (H950)
- G Vista 2 (H740)
- G Vista* (D631)
- Harmony 4 (LM-K400AM)
- Harmony 3 (X420CM)
- Journey (L322DL)
- K92 5G (LM-K920AM)
- K40 (LM-X420AS, LM-X420QN*)
- K30 (LM-X320QMG)
- K20 (M255)
- K10 (K425)
- K51 (LM-K500QM)
- Phoenix 5 (LM-K300AM)
- Phoenix Plus (LM-X410AS)
- Phoenix 4 (LM-X210APM)
- Phoenix 3 (M150)
- Phoenix 2 (K371)
- Premier Pro LTE (LML414DL, LML413DL)
- Premier Pro Plus (L455D)
- Prime 2 (LM-X320AA)
- Q70 (LM-Q620QM)
- Rebel 4 (LML211BL)
- Reflect (L555DL)
- Risio 4 (LM-K300CMR)
- Solo LTE (L423DL)
- Stylo 6 (LMQ730AM)
- Stylo 5 (LM-Q720CS, L722D, LM-Q720QM*)
- Stylo 5+ (LM-Q720AM)
- Stylo 4 (LML713DL, LM-Q710ULM*)
- Stylo 4+ (LM-Q710WA)
- Velvet (LM-G900UM)
- V60 ThinQ (LM-V600AM)
- V40 ThinQ (LM-V405UA)
- V35 (LM-V350ULM)
- V35 ThinQ (LM-V350AWM**)
- V30 (H931)
- V20 (H910)
- V10 (H900)
- Wing (F100VM)
- Xpression Plus 3 (LM-K400AKR)
- Xpression Plus 2 (LM-X420AS8)
- X Venture (H700)

Motorola

- One Fusion+ (XT2067-2)
- One Action (XT2013-4)
- E (XT2052-1)
- E6 (XT2005-5)
- e5 Cruise (XT1921-2)
- E5 Play (XT1921-2A, XT1921-2)
- e5 Supra (XT1924-6)
- E6 (XT2005-5)
- Edge (XT2063-2)
- Edge 5G (XT2063-2)
- G 5G (XT2113-3)
- G Play (XT2093-1, XT2093-4, XT2093-7)
- G Fast (XT2045-3, XT2045-3)
- G Power (XT2041-4, XT2117-4, XT2117-1)
- G Stylus 5G (XT2131-1, XT2131-3, XT2131-4)
- G Stylus (XT2043-4, XT2115-1)
- G Pro (XT2043-8)
- G100 (XT2125-4)
- G30 (XT2129-1)
- G9 Play (XT2083-1)
- G9 Power (XT2091-4)
- G8 Power (XT2041-1)
- G7 (XT1962-1)
- G7 Play (XT1952-4, XT1952-5)
- G7 Plus (XT1965-T)
- G7 Power (XT1955-5)
- G7 Supra (XT1955-5)
- g6 Forge (XT1922)
- g6 Play (XT1922-9)
- G Play 2021 (XT2093DL)
- G Power 2021 (XT2117-2)
- One 5G Ace (XT2113-2, XT2113-5)
- One 5G (XT2075-2, XT2075-5)
- Razr 5G (XT2071-3)
- Razr ((XT2071-2)
- Z4 (XT1980-3)
- Z2 Force Edition (XT1789-04)

Google

- Pixel 5 (GD1YQ)
- Pixel 4a 5G (G025E)
- Pixel 4a (G025J)
- Pixel 4XL* (G020J, G020P, G020Q)
- Pixel 4* (G020I, G020M, G020N)
- Pixel 3a (G020E, G020F, G020G)
- Pixel 3a XL (G020A, G020B, G020C)
- Pixel 3 XL (G013C, G013D)
- Pixel 3 (G013A)
- Pixel 2XL
- Pixel 2 (G011A, G011C)

*Indicates devices that may require a software update to enable HD Voice, Wi-Fi Calling, Video Call, Advanced Messaging or 5G

**AT&T version only

Last updated: : Sept 3, 2021



AT&T

Alcatel

- A3X (A600DL)
- A3 (A509DL)
- A1X (A508DL)
- A1 (A507DL)
- AXEL (5004R)
- Go Flip 3 (A406DL)
- idealXTRA (5059R)
- idealXCITE/ CameoX (5044R)
- IDEAL* (4060A)
- INSIGHT (5005RC)
- OneTouch Allura* (50560)
- ONYX (5008R)
- QUICKFLIP™ (4044C)
- SMARTFLIP (4052R, 4052C)
- TETRA (5041C, 5041CC)
- VOLTA (5002R)

AsusTek

- ROG 3 (ASUS_I003D)
- Zenfone 8 (ASUS_I006D)
- ROG 5 (ASUS_I005D, ASUS_I005DA, ASUS_I005DC)

AT&T

- AXIA (QS5509A)
- Calypso (318AA)
- Cingular Flip IV
- Cingular Flip 2 (4044O)
- Cingular Flip (Q28A)
- Fusion Z (V340U)
- Maestro Plus (V350U)
- Maestro (U202AA, V340U, EA1002)
- Motivate (V341U)
- Radiant Core (U304AA)
- Radiant Max (U705AA)
- Radiant Max 5G (EC211001)

BlackBerry

- KEYone (BBB100-1)
- Priv (STV100-1)

Cricket

- Icon (U304AAC)
- Influence (V350C)
- Ovation 2 (EC1002)
- Vision (QS5509AC)
- Vision 3 (U318AA)
- Wave (FTU18A00QW)

Essential

- PH 1*

HTC

- Desire 626 (OPM9120)
- Desire EYE (OPFH100)
- One A9 (2PQ9120)
- One M8* (OP6B120)
- One M9 (OPJA110)

Huawei

- Ascend XT2 (H1711)
- Ascend XT (H1711)

Kyocera

- DuraForce Pro 2 (E6920)
- DuraForce Pro (E6820)
- DuraForce* (E6560)
- DuraForce XD (E6790)
- Dura XE* (E4710)
- Dura XE Epic (E4830)

Microsoft

- Lumia 950
- Lumia 640 XL
- Surface Duo (1930)

*Indicates devices that may require a software update to enable HD Voice, Wi-Fi Calling, Video Call, Advanced Messaging or 5G
Last updated: Sept 3, 2021



Nokia	
<ul style="list-style-type: none"> 3.1.A (TA1140) 3.1.C (TA1141) 3.1 Plus (TA1124) 	<ul style="list-style-type: none"> C2 Tennen (TA1226) C2 Tava (TA1218) C5 Endi (TA1222) Lumia 830 6300 4G (TA-1324)
OnePlus	
<ul style="list-style-type: none"> Nord N200 (DE2117) Nord N10 (BE2026) Nord N100 (BE2011, BE2013, BE2029) 9 5G (LE2115) 9 Pro 5G (LE2125) 8 5G (IN2010, IN2015) 8 5G UW (IN2019) 	<ul style="list-style-type: none"> 8 (IN2011, IN2013, IN 2017) 8T (KB2000, KB2001, KB2005) 8 Pro (IN2021, IN2023, IN2025) 7T (HD1905) 7 Pro (GM1917) 6T (A6013)
Pepperl+Fuchs	
<ul style="list-style-type: none"> Smart Ex-02 ROW 	
Punkt	
<ul style="list-style-type: none"> MP 02 	
RED	
<ul style="list-style-type: none"> Hydrogen One - (H1A1000/H1T1000) 	

Sonim	
<ul style="list-style-type: none"> RS60 (S6001) XP8 (XP8800) XP7 (XP7700) 	<ul style="list-style-type: none"> XP5s (XP5800) XP3 (XP3800)
Sony	
<ul style="list-style-type: none"> Xperia 5 II (XQ-AS62) Xperia1 II (XQ-AT51) Xperia 1 III (XQ-BC62) Xperia PRO (XQ-AQ62) 	
TCL	
<ul style="list-style-type: none"> T1 Lite (T770B) T1 Pro (T799B) TCL 10 SE (T766S) TCL 10 Pro (T799B) TCL 10L (T770B) 	<ul style="list-style-type: none"> TCL 20S (T7730) TCL 20 Pro 5G (T810S) TCL A30 (51020)
Teracube	
<ul style="list-style-type: none"> 2E (TR20072EQ) Teracube One (TR1907Q) 	
ZTE	
<ul style="list-style-type: none"> Avid 579 (Z5156CC) Blade Spark (Z971) 	<ul style="list-style-type: none"> Maven 2 (Z831) Maven 3 (Z835) Zmax 10 (Z6250CC)

*Indicates devices that may require a software update to enable HD Voice, Wi-Fi Calling, Video Call, Advanced Messaging or 5G
Last updated: Sept 3, 2021



